



Receiver AGC During OTM 339

E-0216 (DSTRcvrAGCba) vs SCET




Static Phase Error During OTM 339

E-0224 (DST_SPE_F_ba) vs SCET




Receiver AGC During The Occultation

E-0216 (DSTRcvrAGCba) vs SCET




Static Phase Error During The Occultation

E-0224 (DST_SPE_F_ba) vs SCET




DST Lock Status During The Occultation

E-0418 (DST_UNLOCK) vs SCET



Rev 180 DST SPE & Lock Status During The Occultation

E-0224 (DST_SPE_F_ba) vs SCET




Date: Wed. Feb. 6, 2013 17:52:40

First Egress Signal
Observed (1-way)

DST in lock
Coherent signals observed
(2-way and 3-way)

E-0418 (DST_UNLOCK) vs SCET



Date: Wed. Feb. 6, 2013 19:59:49

0 = DST in lock
1 = DST out of lock

Static Phase Error Jan 30 to Feb 5

E-0224 (DST_SPE_F_ba) vs SCET

