

Input Files

z0800a_for_S81.cf
 SCLKSCET.00157
 110818AP_LT_11175_17265.TXT
 CAS_11066_17263.VP
 110818BP_OP_11175_17265.TXT
 S81_SIP_PORT1_GEOEPOCHS_130513.sasf
 S81_SIP_PORT1_RIDEREPOCHS_130620.sasf
 SP_S81_SIP_PORT2_DATAPOL_130621.sasf
 SP_S81_SIP_PORT1_PDT_130620.sasf
 ULO_S81_SIP_PORT2_ATT_130701.sasf
 ULO_S81_SIP_PORT2_SFOS_130701.sasf
 CAPS_S81_SIP_PORT2_180702.sasf
 CDA_S81_SIP_PORT1_130618.sasf
 CIRS_S81_SIP_PORT2_130701.sasf
 INMS_S81_SIP_PORT1_130618.sasf
 ISS_S81_SIP_PORT2_130702.sasf
 MAG_S81_SIP_PORT2_130627.sasf
 MIML_S81_SIP_PORT1_130618.sasf
 NAV_S81_sip_port1_130618.sasf
 RPWS_S81_SIP_PORT2_130702.sasf
 RSS_S81_SIP_PORT2_130702.sasf
 UVIS_S81_SIP_PORT1_130617.sasf
 VIMS_S81_SIP_PORT2_130702.sasf
 SI_S81_SIP_PORT2_130625.sasf
 vimsiops_S81_SIP_PORT1_130618.sasf
 AACCS_S81_SIP_PORT2_130701.sasf
 CDS_S81_SIP_PORT2_130701.sasf
 OPMODE_S81_SIP_PORT2_130701.sasf

This Merge Has No Files From

ISSIOPS
 RADAR

IVD Files

(none)

SPAM

ERROR NUMBER	RESPONSIBLE TEAM	TIME	REQUEST	PROBLEM	PROPOSED SOLUTION	Disposition
EARTH POINT ERRORS						
(none)						
VELOCITY AND ACCELERATION ERRORS						
SP_RCS_RWA_Error_1	SP	2013-303T06:44:54.000	SP_198EA_M34BWGNON303_PRIME	Exceeding RWA slow rates. Rates used 1.25,1.54,2.6,0.009,0.009,0.022		
COMMANDS EXPANDED OUTSIDE OF SEQUENCE						
(none)						
TARGET OPTION LABEL ERRORS						
SP_Label_Error_7	AACS/SCO	2013-343T15:31:23	ENGR_199SC_YBIASCAL001_AACS	Same label 79 used on succeeding RA_DEC with different parameters	Use a different label for this RA_DEC	Use a different label for this RA_DEC. SCO to fix.
SP_Label_Error_8		2013-343T17:00:55	SP_199EA_G34HEFNON443_PRIME	Same label 79 used on succeeding RA_DEC with different parameters	Use a different label for this RA_DEC	
SP_Label_Error_9	AACS/SCO	2013-343T18:01:10	ENGR_199SC_YBIASCAL002_AACS	Same label 79 used on succeeding RA_DEC with different parameters	Use a different label for this RA_DEC	Use a different label for this RA_DEC. SCO to fix.
SP_Label_Error_10		2013-343T19:30:55	SP_199EA_G34HEFNON543_PRIME	Same label 79 used on succeeding RA_DEC with different parameters	Use a different label for this RA_DEC	
PRECISION ERRORS						
(none)						
Duplicate Epochs						
LMB Warnings						
SEQGEN Violations Summary						
sameSecondCommandConflict-151	SCO	2013-352T02:32:01	SP-SMT_200NA_OBSERV352_NA, ENGR_200SC_ORSRWA352_PPS	2MOD, 2XTWTA	Should not occur at the same time	SCO move 2XTWTA (see SEQGEN-1)

SEQGEN-1		2013-352T02:32:01.000	SP-SMT_200NA_OBSERV352_NA	ERROR: FR02E4 Violation (Part 1)- The RFS processor must not be commanded more than once per second.		SCO move 2XTWTA (see sameSecondCommandConflict-151)
SMT ERRORS						
AP DOWNLINK CHECKS						
SPASS//SASF COMPARE						
CIMS_SPASS_SASF_0311	ENGR	2013-295T23:21:00	ENGR_198SC_KPTYBIAS295_PRIME	The CIMS request does not correspond to a request in the SASF	Check your CIMS and SASF request names	BOS bias missing from SCO file
CIMS_SPASS_SASF_0315	CIRS	2013-333T11:30:00	CIRS_199RI_NP50L30007_PIE	SASF does not match the SPASS: Primary BV: CIRS_FP1 (SASF) <> NEG_Y (SPASS)	Fix pointing commands to match the SPASS	
CIMS_SPASS_SASF_0327	CIRS	2013-360T06:30:00	CIRS_200OT_FOV34CAL001_PRIME	SASF does not match the SPASS: Primary BV: CIRS_FP3 (SASF) <> CIRS_FP3 (SPASS)	Fix pointing commands to match the SPASS (possibly a typo?)	