

Input Files

z0810f_for_S82.cf
 SCLKSCET.00158
 110818AP_LT_11175_17265.TXT
 CAS_11066_17263.VP
 110818BP_OP_11175_17265.TXT
 S82_SIP_PORT1_GEOEPOCHS_130711.sasf
 S82_SIP_PSV_RIDEREPOCHS_131115.sasf
 ulo_cyclic_z0820c_in.sasf
 SP_S82_SIP_PORT3_PDT_131021.sasf
 smt_z0820c_in.sasf
 ulo_att_z0820c_in.sasf
 ulo_sfos_z0820c_in.sasf
 cda_z0820c_in.sasf
 cirs_z0820c_in.sasf
 INMS_S82_SIP_PORT2_130904.sasf
 ISS_S82_SIP_PORT3_131016.sasf
 mag_z0820c_in.sasf
 mimi_z0820c_in.sasf
 NAV_S82_SIP_PORT2_UG_130918.sasf
 radar_z0820c_in.sasf
 rpws_z0820c_in.sasf
 RSS_S82_SIP_PORT3_131021.sasf
 uvis_z0820c_in.sasf
 VIMS_S82_SIP_PORT2_UG1_130923.sasf
 issiops_z0820c_in.sasf
 SJ_S82_SIP_PORT2_130830.sasf
 vimsiops_z0820c_in.sasf
 sco_z0820c_in.sasf

This Merge Has No Files From

CAPS

IVD Files

RADAR_S82_PSV_T98_131114_Lp3.ivd

SPAM

ERROR NUMBER	RESPONSIBLE TEAM	TIME	REQUEST	PROBLEM	PROPOSED SOLUTION
AP DOWNLINK CHECKS					
S82000973	SP	2014-025T08:51:00	SP_201NA_G34BWGOTP025_SP	SP_201NA_G34BWGOTP025_SP DSS code is inconsistent with complex/antenna	SP to fix
S82000975	SP	2014-028T13:41:00	SP_201SA_C70METNON028_SP	SP_201SA_C70METNON028_SP should be SP-owned, NA-targeted, and ride along with an SP event	SP to change target
SPASS//SASF COMPARE					

CIMS_SPASS_SASF_1213	ENGR	2013-362T01:53:00	ENGR_200SC_KPTYBIAS462_PRIME	The CIMS request ENGR_200SC_KPTYBIAS462_PRIME was not found in the SASF when searching by Name. Using ENGR_200SC_KPTYBIAS362_PRIME for comparisons	SCO to change CIMS name to match SASF name (that is, from 462 to 362)
----------------------	------	-------------------	------------------------------	--	---